



IMSA PENALTY NOTICE
SP - 23 - 20



ENTRY

95
GS

TYPE: Sporting

EVENT: CHEVROLET GRAND PRIX

SERIES: IMPC

TEAM: Turner Motorsport

ENTRANT: Will Turner

REPRESENTATIVE:

DRIVER:

AFFECTED PARTY: N/A

INFRACTION

OFFICIAL:

The Official listed above has reviewed the following matter and determined it to be a breach of the IMSA RULES committed by the Team and imposes the penalty(ies) listed below.

DATE & TIME: 7/8/2023 8:20:00 PM **LOCATION:** Technical Inspection

REGULATION: 37.7.1. (SSR) An Entrant must not demonstrate a full refueling time less than the Minimum Full Refueling Time listed in the class-specific BoP table subject to and as verified by a single Minimum Full Fill Refueling Time Audit

FACTS: Car 95 was found to have a refueling time less than the minimum per IMPC TB 23-22

PENALTY

FINE: NA

CHANGE: Car is moved to the back of the Class

RETURN TROPHY

SIGNATURES

Approved by:

Matthew Kurdock

7/8/2023 8:36:08 PM

Delivered by:

Eric Haverson

7/8/2023 8:41:16 PM

Received by:

Will Turner
Turner Motorsport



IMSA PENALTY NOTICE
SP - 23 - 20



REGULATION # SR & SSR

37.7.1. (SSR) An Entrant must not demonstrate a full refueling time less than the Minimum Full Refueling Time listed in the class-specific BoP table subject to and as verified by a single Minimum Full Fill Refueling Time Audit